

P0155 - P0159: Testing and Inspection

P0158

For diagnosis of code P0158, refer to chart:

P0158 - O2 Circuit High Voltage (Bank 2, Sensor 2)			
Description:		See the description for DTC P0132.	
Possible Causes:		See the possible causes for DTC P0132.	
Diagnostic Aids:		See the diagnostic aids for DTC P0132.	
Application	Key On Engine Off	Key On Engine Running	Continuous Memory
All	—	GO to Pinpoint Test DW.	GO to Pinpoint Test DW.

P0158

If there is no link in the chart then:

- This code is not a valid code for this vehicle
- Or information published by the manufacturer for this vehicle did not include this code
- Or ALLDATA has not added the information for this code yet

For complete diagnosis of the system, follow this link: See: Powertrain Management/Computers and Control Systems/Testing and Inspection