

P0175 - P0179: Testing and Inspection

For diagnosis of code P0175, refer to chart:

P0175 - System Too Rich (Bank 2)			
Description:		See the description for DTC P0172.	
Possible Causes:		See the possible causes for DTC P0172.	
Diagnostic Aids:		See the diagnostic aids for DTC P0172.	
Application	Key On Engine Off	Key On Engine Running	Continuous Memory
All	—	—	GO to Pinpoint Test H.

P0175

If there is no link in the chart then:

- This code is not a valid code for this vehicle
- Or information published by the manufacturer for this vehicle did not include this code
- Or ALLDATA has not added the information for this code yet

For complete diagnosis of the system, follow this link: See: Powertrain Management/Computers and Control Systems/Testing and Inspection