

1998 FORD F-150

2FTZF1725WCA63793

Odometer: 165,945 kms

6 Confirmed Codes

- P0135** O2 Sensor Heater Circuit Bank 1 Sensor 1
- P0141** O2 Sensor Heater Circuit Bank 1 Sensor 2
- P1152** Lack of (HO2S21) Switch Sensor indicates Rich
- P0155** O2 Sensor Heater Circuit Bank 2 Sensor 1
- P0161** O2 Sensor Heater Circuit Bank 2 Sensor 2
- P1132** (HO2S11) not switching correctly. Sensor indicates rich.

6 Pending Codes

- P0135** O2 Sensor Heater Circuit Bank 1 Sensor 1
- P0141** O2 Sensor Heater Circuit Bank 1 Sensor 2
- P1152** Lack of (HO2S21) Switch Sensor indicates Rich
- P0155** O2 Sensor Heater Circuit Bank 2 Sensor 1
- P0161** O2 Sensor Heater Circuit Bank 2 Sensor 2
- P1132** (HO2S11) not switching correctly. Sensor indicates rich.

7 Powertrain Control Module Codes

- P0135** O2 Sensor Heater Circuit Bank 1 Sensor 1
- P0141** O2 Sensor Heater Circuit Bank 1 Sensor 2

- P0155** O2 Sensor Heater Circuit Bank 2 Sensor 1
- P0161** O2 Sensor Heater Circuit Bank 2 Sensor 2
- P1132** (HO2S11) not switching correctly. Sensor indicates rich.
- P1152** Lack of (HO2S21) Switch Sensor indicates Rich
- P0460** Fuel Level Sensor "A" Circuit

1 Restraint control Module Code

- B1867** Battery Power Supply (ECU) Circuit Short To Ground

Disclaimer: This information is provided without warranty and is subject to the Terms of Use posted at www.bluedriver.com/eula.html. Reproduction of this information or any portion thereof constitutes infringement of copyright.