

C142 (BU)**12B637**HEATED OXYGEN SENSOR (HO2S) #12
(9G444)

Pin	Circuit	Gauge	Circuit Function	Qualifier
1	CE233 (WH-O2)	18	Heated oxygen sensor (HO2S) #12 heater	
2	CBP44 (VT)	20	Voltage supplied in Start and Run (overload protected)	
3	VE731 (YE-GN)	18	Heated oxygen sensor (HO2S) #12 Input	
4	RE408 (GN-WH)	20	Signal return	

C142