

**C141 (BU)****12B637**HEATED OXYGEN SENSOR (HO2S) #22  
(9G444)

Pin	Circuit	Gauge	Circuit Function	Qualifier
1	CE234 (BU-WH)	18	Heated oxygen sensor (HO2S) #22 heater	
2	CBP44 (VT)	20	Voltage supplied at Start and Run (overhead protected)	
3	VE733 (WH)	18	Heated oxygen sensor (HO2S) #22 input	
4	RE405 (GN-WH)	20	Signal return	

C141