

Inspection Report

	Excellent Condition
	May Require Future Attention
	Requires Immediate Attention

GENERAL INFORMATION			
Agent	Andy Turner	Inspector	Andy Turner
Report Date	Thursday, April 21, 2016	Inspection Date	Sunday, April 17, 2016
Year	2010	VIN	1FMCU0D72AKD42009
Make	Ford	Mileage	67,116
Model	Escape	Engine	Duratect® 25 - 2.5L I-4
Trim	XLT FWD I-4 (Rapid Spec 202A)	Transmission	6-Speed Automatic
Last Maintenance	4/1/2016 @ 67,079 miles	Future Maintenance	10/1/2016 @ 72,079 miles
State Inspection Due	Monday, September 5, 2016	Registration Due	Wednesday, August 31, 2016

VEHICLE PHOTO(S)	COMMENTS
 	<p>I thoroughly enjoyed inspecting this vehicle for you today! In general, the vehicle is in OKAY to EXCELLENT condition. There was a reasonable amount of scrapes, scratches, dents, dings, etc. on the vehicle's body and interior paneling which is expected with a vehicle of this age and mileage. This should be considered typical with respect to normal wear and tear on a daily driver. Its more important to note that the vehicle has been well cared for and runs extremely well. Most of the vehicle's concerns are cosmetic and/or not essential components.</p>
	<p>The vehicle's moon roof automatic open/close feature is inoperable. However, it can be manually, electronically opened and closed.</p> <p>It is recommended to complete a polish and reconditioning detail for the vehicle's full potential since it runs very well, shifts on point, has excellent performance, visibility, fully loaded features, etc. A chassis lube (if applicable), oil and filter change service was completed recently.</p>

OVERALL RESULTS					
Road Test	Excellent	Engine Bay	Okay	Under Carriage	Excellent
Body	Okay	Glass	Okay	Rims & Tires	Okay
Interior Trim	Okay	Carpet	Excellent	Upholstery	Okay
Mechanical	Excellent	Electrical	Okay (Moon Roof)	Gauges	Excellent
Audio	Excellent	Trunk/Cargo	Excellent	Cleanliness	Reconditioning

MECHANICAL & ROAD TEST					
Engine Bay	Okay (Dirty)	Oil Leaks	None	Oil Condition	Excellent
Windshield Wsh Fl	Excellent	Brake Fluid	Excellent	Power Steering Fluid	Excellent
Headlamp Wsh Fluid	Not Equipped	Coolant Recovery Fl	Excellent	Air Filter	Okay
Trans Fluid	Excellent	Trans Clutch/Shifts	Excellent	Trans Noise	None
Exhaust Fitment	Excellent	Exhaust Leaks	None	Exhaust Smoke	None
Starting	Excellent	Idle	Excellent	Drive Belt	Excellent
Battery	Excellent	Battery Terminals	Excellent	Visiblity	Excellent
Suspension	Excellent	Steering	Excellent	Drive Alignment	Excellent
Engine Noise	None	Road Noise	None	Wind Noise	None
Engine Temp	Excellent	Brake System	Excellent	Emergency Brake	1,500 RPM
Head Light Alignment	Excellent	Acceleration	Excellent	Performance	Excellent
Front Left Tire PSI	32	Front Right Tire PSI	32	Spare Tire PSI	Not Tested
Rear Left Tire PSI	32	Rear Right Tire PSI	32	Hoses/Clamps	Excellent
DRW Left Tire PSI	Not Equipped	DRW Right Tire PSI	Not Equipped	Lines/Clamps	Excellent

Inspection Report

	Excellent Condition
	May Require Future Attention
	Requires Immediate Attention

EXTERIOR CONDITION					
Under Carriage	Excellent	Front Right	Okay	Front Left	Okay
Hood	(2) Med Dents + Chips	Front Bumper	(+) Sm Scratches <1"	Grill	Okay
Panel Color Match	Excellent	Paint Depth Gauge	Not Tested	Rust/Corrosion	None
Panel Alignment	Excellent	Weather Striping	Excellent	Swirls/Holograms	Reconditioning
Front Lenses	Okay (Faded+Chip)	Fog Lenses	Excellent	Front Plate Area	Excellent
Front Wiper(s)	Excellent	Rear Wiper(s)	Excellent	Wiper Washers	Excellent
Left Side Mirror	(2) Scrapes 3"	Right Side Mirror	Excellent	Antenna	Base Faded
Windshield	(3+) Sm Chips	Front Right Glass	Excellent	Front Left Glass	(+) Vertical Scratches
Front Left Door	Sm Scratches + Ding	Front Right Door	Okay	Roof	Okay
Rear Left Door	(+) Sm Scratches <2"	Rear Right Door	(+) Sm Scratches <2"	Door Handles	Excellent
Side Left Rails	Excellent	Side Right Rails	Excellent	Door Locks	Excellent
Rear Right Glass	Excellent	Rear Left Glass	Excellent	Rear Glass	Excellent
Rear Left (Qtr)	Okay	Rear Right (Qtr)	Okay	Trunk/Gate	Okay
Rear Lenses	Excellent	Trim/Plastic	Okay	Rear Plate Area	Excellent
Rear Bumper	(+) Scrapes <3"	Fuel Area/Cap	Excellent	Bed/Liner	Not Equipped
Front Left Rim	(+) Sm Scratches <1"	Front Right Rim	(+) Sm Scratches <1"	Spare Rim	Okay
Rear Left Rim	Excellent	Rear Right Rim	(+) Sm Scratches <1"	Spare Tire	Excellent
Front Left Tire	Excellent	Front Right Tire	Excellent	Rim Lugs	(1) Lug Not Matching
Rear Left Tire	Excellent	Rear Right Tire	Excellent	Rim Locks	Not Equipped
Badging/Emblems	Excellent	Decals	Excellent	Paint	Reconditioning

INTERIOR CONDITON					
Dashboard	Excellent	Glove Box	Excellent	Keyless Entry	Excellent
Center Stack	Okay	Center Console	Okay	Trim	Light Scratches
Front Left Seat	Sm Stains	Front Center Seat	Not Equipped	Front Right Seat	Sm Stains
Mid Left Seat	Stain	Mid Center Seat	Excellent	Mid Right Seat	Excellent
Rear Left Seat	Not Equipped	Rear Center Seat	Not Equipped	Rear Right Seat	Not Equipped
Carpet Front	Okay	Carpet Rear	Excellent	Carpet Trunk	Excellent
Front Left Door	(+) Sm Scrapes	Front Right Door	(+) Sm Scrapes	Headliner	Okay
Rear Left Door	Sm Scratch <2"	Rear Right Door	(+) Sm Scrapes	Hood Release	Excellent
Vanity Mirrors	Excellent	Rear View Mirror	Excellent	Head Rests	Excellent
Seatbelts	Excellent	Door(s) Open/Close	Excellent	Trunk Open/Close	Excellent
Jack	Excellent	Tools	Excellent	First-Aid Kit	Not Equipped
Mats	Okay	Manuals	Excellent	Smell	Okay

ELECTRICAL & FUNCTIONALITY					
Speedometer	Excellent	Odometer	Excellent	Tachometer	Excellent
Temperature Gauge	Excellent	Oil Pressure Gauge	Not Equipped	Fuel Level Gauge	Excellent
Trans Temp Gauge	Not Equipped	Hybrid/Elec Gauge	Not Equipped	Boost Gauge	Not Equipped
Voltmeter Gauge	Not Equipped	E-Brake Minder	Excellent	Directional Minder	Excellent
Door Open Minder	Excellent	Trunk Open Minder	Not Tested	Cluster LCD/Screen	Excellent
Pking Lights Minder	Excellent	Head Lights Minder	Excellent	Highbeam Minder	Excellent
Front Fog Minder	Excellent	Rear Fog Minder	Not Equipped	Gear Selector Minder	Excellent
Passenger Airbag Lt	N/A	Seatbelt Minder	Excellent	Pass Seatbelt Minder	Excellent
Check Engine Light	None	Service Minder	None	Trip Computer	Excellent
Radio	Excellent	CD Player	Not Tested	Media Players	Not Equipped
Bluetooth Audio	Excellent	Auxillary Audio	Not Tested	Headsets	Excellent
Sun/Moon Roof	Auto Feat Inoperable	Heater Operation	Excellent	A/C Operation	Excellent
Cigarette Lighter	Not Tested	Front Aux Power	Not Tested	Mid Aux Power	Not Tested
Cruise Control	Excellent	Rear Aux Power	Not Tested	Other Aux Power	Not Equipped
Convertible	Not Equipped	Heated Seats	Not Equipped	Ventilated Seats	Not Equipped
Power Windows	Excellent	Power Door Locks	Excellent	Power Seats	Excellent
Windshield Washer	Excellent	Rear Window Washer	Excellent	Head Light Washer	Not Equipped
Head Lights	Excellent	Reverse Lights	Excellent	Fog Lights	Excellent
Brake Lights	Excellent	Parking Lights	Excellent	Directional Lights	Excellent
Hazard Lights	Excellent	Interior Lights	Excellent	Horn	Excellent